6. Tare function: Don't put any tray or bowl on scale weighing platform before it is turned on. After the scale is turned on, put the tray or bowl on the scale weighing platform, press the "ON/ZERO/OFF" button when the weight is stable. Then you can put food to be weighed on the tray or in the bowl.

LOW BATTERY AND OVER LOAD INDICATOR

When the battery power is too low to work normally, the LCD will indicate LO under this condition please replace the battery.

When the scale is over loaded (over 5000g), the LCD will show $\boxed{\mathsf{Err}}$ mark as over load indicator.

MAVERICK LIMITED 90 DAY WARRANTY

Maverick Industries Inc. warrants this product to be free of defects in parts, materials and workmanship for a period of 90 days, from date of purchase. Should any repairs or servicing under this warranty be required, contact Maverick Customer Service by mail or phone for instructions on how to pack and ship the product to Maverick's National Service Center located as follows:

Maverick Customer Service
94 Mayfield Ave.
Edison NJ 08837
Email –help@maverickhousewares.com

Do not send any parts or product to Maverick without calling and obtaining a Return Authorization Number and instructions.

This warranty is VOID if instructions for use are not followed; for accidental damage; for commercial use; for damage incurred while in transit; or if the product has been tampered with.

This warranty gives you specific legal rights and you may also have other rights which vary from state to state.

www.maverickhousewares.com

INSTRUCTION MANUAL FOR ELECTRONIC KITCHEN SCALE
(MODEL: KS-05)

Please read this instruction manual carefully before using the product for the first time to ensure its accuracy & reliability.

MAIN FEATURES

◆ Max. capacity: 5000g
◆ LCD display size: 40x18mm
◆ Five units of measure: g/oz/lb:oz/fl.oz./ml
◆ ABS/AS food safe plastic
◆ Increment : 1g
◆ Auto-zero/off function
◆ Low battery indicator
◆ Over load indicator
◆ Tare function

OPERATING INSTRUCTIONS

1. Open the battery box cover (back side of the scale) and slide 1 1.5V CR2032 battery unto terminals with (+) side of battery facing up.

2. Place the scale on a hard & flat surface.

3, Press the "ON/ZERO/OFF" button to switch on the scale. The LCD will turn on and auto-zero. Place the food in the center of the glass platform.

4. Changing units of measure: switch on the scale and press the "MODE" button to change from "g" , "oz", "ml" "fl.oz."and "lb:oz".

5. To turn off: press the "ON/ZERO/OFF" button for about three seconds after you finished weighing, the LCD will be switched off. Should you forget to switch off by manual operation, scale will automatically switch off after about 30 seconds' non-weighing action.